

Alston & Bird LLP

CQC

Bank of America Plaza 101 South Tryon Street, Suite 4000 Charlotte, NC 28280-4000 (704) 444-1000 Fax (704) 444-1111

October 17, 2005

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re:

United States Patent for System And Method For Remotely

Detecting Electric Arc Events In A Power System
Application No. 10/662,565; Filed September 15, 2003
Patent No. 6,943,558; Issued September 13, 2005

Our File 038190/255097

Sir:

It is respectfully requested that a Certificate of Correction be issued for the above-identified patent, in accordance with 37 C.F.R. §1.322. This request is made in order to correct the mistakes incurred through the fault of the United States Patent and Trademark Office ("USPTO").

The mistakes appearing in the patent are set forth on the Certificate of Correction enclosed herewith, with an additional copy thereof and a postal card being enclosed in accordance with the present USPTO practice.

Respectfully submitted,

Andrew T. Spence

Registration No. 45,699

OCT 2 6 2005

Of Correction

ATS:mf Enclosures CLT01/4756119v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,943,558 B2

Page 1 of 1

DATED

September 13, 2005

INVENTOR(S):

Hale et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 13,

Line 9, after "shutdown can be prevented." insert the following:

-- For more information on such a damaged wire detector, as well as the system including both the arc fault detector 16 and the damaged wire detector, see U.S. Patent Application No. entitled: System, Damaged Wire Detector and Method for Remotely Detecting and Locating Arc Fault Events in A Power System, filed concurrently herewith; and U.S. Patent Application No. entitled: System, Supplemental Protection Module and Method for Remotely Detecting and Locating Faults in A Power System, filed concurrently herewith, the contents of both of which are hereby incorporated by reference in their entirety. --.

MAILING ADDRESS OF SENDER:

6,943,558 B2

ALSTON & BIRD LLP Bank of America Plaza

101 South Tryon Street, Suite 4000

Charlotte, NC 28280-4000

Tel Charlotte Office (704) 444-1000

No. of add'l. copies



FORM PTO 1050 (REV. 3-82)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,943,558 B2

Page 1 of 1

DATED

September 13, 2005

INVENTOR(S):

Hale et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 13,

Line 9, after "shutdown can be prevented." insert the following:

-- For more information on such a damaged wire detector, as well as the system including both the arc fault detector 16 and the damaged wire detector, see U.S. Patent Application No. entitled: System, Damaged Wire Detector and Method for Remotely Detecting and Locating Arc Fault Events in A Power System, filed concurrently herewith; and U.S. Patent Application No. entitled: System, Supplemental Protection Module and Method for Remotely Detecting and Locating Faults in A Power System, filed concurrently herewith, the contents of both of which are hereby incorporated by reference in their entirety. --.

MAILING ADDRESS OF SENDER:

PATENT NO.

6,943,558 B2

ALSTON & BIRD LLP Bank of America Plaza 101 South Tryon Street, Suite 4000

Charlotte, NC 28280-4000

Tel Charlotte Office (704) 444-1000

No. of add'l. copies @ 30¢ per page



FORM PTO 1050 (REV. 3-82)